

# SAFETY DATA SHEET

CIBA-GEIGY Corporation Composite Materials Department 10910 Talbert Avenue Fountain Valley, CA 92708 (714) 964-2731

TRADE NAME:

R-922

CHEMICAL FAMILY/NAME:

Multifunctional Epoxy-Impregnated

Carbon Fiber

PRODUCT TYPE:

Resin-Impregnated Fiber

Oma 2197 \$2/83

The information and recommendations contained herein are based upon data believed to be correct. However, no guarantee or warranty of any kind expressed or implied is made with respect to the information contained herein.

I.	HAZARDOUS INGREDIE		<i>%</i> ]	ME WEIGHTED AVERAGE:		
	N					
II.	PHYSICAL DATA		•	(9)		
	BOILING POINT (°C)	N/A	SOLUBILITY IN WA	TER °C	None of The	
	MELTING POINT (°C)	· N/A	SPECIFIC GRAVITY	(H <sub>2</sub> O = 1)	1.2	
	VAPOR DENSITY (AIR = 1)	N/A ·	PERCENT VOLATIL	E BY VOLUME (%	< 1	
	VAPOR PRESSURE (mm Hg) 20 °C	<0.1	EVAPORATION RAT	TE =1	N/A	
	pH	N/A	DECOMPOSITION T	EMPERATURE (°	C)	
	APPEARANCE AND ODOR	Black prepreg, no odor.				
III.	FIRE AND EXPLOSION HAZARD DATA					
	FLASH POINT °F (Method Used) Closed cup	-		FLAMMABLE LIMITS IN AIR		
	DOT CLASS	Not regulated		DOT No.		
	EXTINGUISHING MEDIA	Water spray, foam, CO <sub>2</sub> or dry chemical.				
	SPECIAL FIRE FIGHTING PROCEDURES	Use self-contained breathing apparatus.				

IV. REACTIVITY DATA

UNUSUAL FIRE AND

**EXPLOSION HAZARDS** 

STABILITY	UNSTABLE		CONDITIONS TO AVOID	$\neg$
	STABLE	X	Temperature over 300°F.	
INCOMPATIBILITY (N Acids, bases,	Materials to Avoid) and oxidizing	ager	its	
HAZARDOUS DECOM Oxides of carb			other unknown compounds of nitrogen.	
HAZARDOUS	MAY OCCUR		CONDITIONS TO AVOID	$\dashv$
POLYMERIZATION	WILL NOT OCCUR	X	Negligible risk. Excess heat (over 300°F).	

Decomposition and combustion products may be toxic.

## V. HEALTH HAZARD DATA

TIME WEIGHT	ED	AVERAGE
ORAL: LD50		Ca 5400 Mg/Kg,
DERMAL: LE	50	
SKIN IRRITAT	101	u: (minimal)
EYE IRRITATI	ON	
SENSITIZATIO	N:	·
INHALATION:	L	C <sub>50</sub>
EFFECTS OF C	OVE	REXPOSURE
Prolonged	0	r repeated skin contact may cause irritation/sensitization and dermatitis.
EMERGENCY	& F	IRST AID PROCEDURES:
INHALATION	:	Operators affected by inhalation of vapors should be taken into fresh air
		and made to rest while medical attention is called.
INGESTION	:	Immediately rinse mouth with water. If swallowing has occurred, drink
		plenty of water. Seek medical attention promptly.
SKIN	:	Wash with soap and water. Any material adhering to skin should be removed
		with resin-removing creams. DO NOT USE SOLVENTS!
EYES		Flush eyes with water for 15 minutes. Get medical attention.
	•	Tidair cycs with water for is annues.
OTHER		

## VI. SPILL OR LEAK PROCEDURES

•	STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED	N/A
E ST	WASTE DISPOSAL METHOD	Dispose in accordance to federal, state, and local regulations.  Landfill, Do Not Incinerate.
i	RCRA STATUS	Not a hazardous waste under RCRA (40CFR 261)

#### VII. SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION	During machining, where necessary to protect against dusts.
PROTECTIVE GLOVES	Use of white cotton gloves is recommended.
OTHER PROTECTIVE EQUIPMENT	Skin barrier creams and clothing protection of exposed skin areas recommended during machining.
EYE PROTECTION	Should be worn during machining to protect eyes from dust.
VENTILATION:	Curing of prepreg materials and subsequent machining of parts should be carried out in areas with good ventilation.

## VIII. SPECIAL PRECAUTIONS

DI DOMINI I I I I I I I I I I I I I I I I I I	
PRECAUTIONS TO BE TAKEN IN HANDLING, SHIPPING, AND STORING	Handling techniques must ensure that no uncured epoxy material comes in contact with eyes or skin. Operators should wear gloves and full-length clothing.  Work area should be well ventilated.  Eating, drinking, and smoking in work area must be prohibited.  Cleanliness and tidiness are of utmost importance.  Store materials in cool dry place.  Store away from food and food containers.

			Rich R
ATE	9-28-83	ISSUED BY:	sear the